

GOVERNMENT OF TELANGANA STATE DISASTER RESPONSE & FIRE SERVICES DEPARTMENT FIRE AUDIT LETTER



From
The District fire officer,

30/08/2022

To,

SRINIVAS VARMA,

ARMY PUBLIC

SCHOOL.R.K.PURAM.SECUNDERABAD.,

Sir,
Sub:

TELANGANA STATE DISASTER RESPONSE & FIRE SERVICE

DEPARTMENT -.

Issue of Fire Audit status report of ARMY PUBLIC

SCHOOL, ARMY PUBLIC

SCHOOL, R.K.PURAM.SECUNDERABAD./ARMY PUBLIC

SCHOOL.R.K.PURAM.SECUNDERABAD.
Malkajgiri/Malkajgiri/Medchal, Hyderabad - Regarding.

1. Acknowledgement No15972022/FireAuditdt.30/08/2022

2. Fire Audit Inspection Committee Report, Hyderabad Ack. No. 15972022/FireAudit, dt.

The Fire Audit Inspection committee, vide reference cited (2) has inspected the Building/Premises of ARMY PUBLIC SCHOOL, ARMY PUBLIC SCHOOL.R.K.PURAM.SECUNDERABAD./ARMY PUBLIC SCHOOL.R.K.PURAM.SECUNDERABAD.-Malkajgiri/Medchal on 30/08/2022 and submitted the following report.

2) The builder has constructed the building with 1 Ground, 1 Floors, with a height of 9.00 Meters for EDUCATIONAL B-1 Schools up to senior secondary level Occupancy and requested for Fire Audit report.

3) Open Spaces: The builder provided the following open spaces all around the building. Deficit Remarks Open space Provided Required as per GO(168) Sl.No Side 0.00 6.00 6.00 North 0 a 1 0.00 6.00 6.00 South 2 0 0.00 6.00 6.00 3 East 0.00 6.00 6.00 West 4 Deficit Provided Required b Sl. No Gate Width As per NBC 2016 0.00 6.00 6.00 Entry gate width 1 0.00 5.00 4.50 Entry Gate Head Clearance 2 0.00 6.00 6.00 Exit Gate Width 3 mined in 10.00 5.00 4,50 Exit Gate Head Clearance 4 0.00 12.00 12.00 Abutting Road Width(In Mtrs): 5

Travel Distance o Item / Description	Required (Not More than in Mtrs.)	Provided	Deficit
Farthest point (Most Remote Point) With in a storey or a mezzanine	30.00	29.00	0.00
floor to the door to an Exit. The Dead end of the corridor length in exit access. (6 mtrs for Educational, Institutional and Assembly, 15mtrs for other	6.00	6.00	0.00